

Date: 28.10.2020
It is certified that an inspection team headed by Rasamande Baral
Hest. Engineer RWS & Section Biss (Name of Officers
RWSS Dim. R gue hele (Name of
Department/Office) inspected the H.A. ENWLISH SCHOOL"
Amthabad near Aashiyana Colony, Biska (Name & Address of the School) on 228 1
and found that the H. A. GARLICH COHOL
Aminabad rear Austriguna (Alony Brisis (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is
maintaining the hygienic sanitation condition in the school building & the campus as per the
norms prescribed by the Central/State/U.T Govt.
The above valid for a period of <u>One year</u> .
Signature with Seal: Name: Rayananda Ba
Name: Rayanande Ba
Designation: Assistant Engineer R.W.S & S. Soction
To H.A. ENALISH SCHOOL Biors
Aminabad new Aashiyana (A)ony
Bisra, Not. Sundangel (odsla)
(Name & Address of the Institution)